

Date: September 16, 2019		FAX THIS SHEET IN TO THE OFFICE AFTER YOUR MEETING!!!	
<u>Project Number#:</u>	<u>Job Name:</u>	<u>Person Conducting Meeting:</u>	

Best Practices

Best Practices are practical solutions to situations we have in the work place. They not only make our work place safer, but help us to be more efficient. Best practices are not meant to be kept a secret. These ideas are to be shared in making us a better drywall/plastering company versus our competition. I have included a few "best practice" photos on the backside of this sheet that I've seen on our jobsites recently. Please submit any ideas you have to help make us better on September's safety suggestion sheet (*payroll insert*).

Last week's Bonus Question: What are three hazards we see in Photo #3 on the backside of this weeks TBT

Answer: The guardrail was not put into place when the worker went for lunch. Ladder is not tied off. Generator exhaust is exposing worker in bottom of elevator pit to Carbon Monoxide. Housekeeping. Crew not discussing their work plan before they started in the morning. What other items did you find?
Would this be considered a "confined space"?

Tuesday, September 17th the Safety Committee will be drawing 20 - \$500 VISA card winners for completing the months of July & August without a Lost Time Accident!

For **inspection packets or repair tags** call **Dave Sangren @ (612) 644-3136** to have some delivered to your jobsite.

Any questions give Sturg a call (612) 221-8603

PLEASE PRINT YOUR NAME!!!

_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Visit our website: www.olympiccompanies.com

Comments:

**As of September 12, 2019 we have worked 21 days without a Lost Time Injury.
We have safely worked 31,528 hours towards our ATV goal of 150,000 hours!**

Toolbox Talks winner for last week: **Jesse Vadnais @ Dayton's, Antonio Carrillo @ Warehouse & Dave O'Brien @ McGough HQ**

This week's Bonus Question: **Who were the 3 winners from TBT last week?**

Hint: **See TBT**

Best Practices



Protect our LP tanks from traffic



RED TAG damaged equipment




PAINT trip hazards



Post safety signage



Organized gang box



Proper ventilation



Tie wire to secure a pail from falling from a scaffold